ENGINEERING CHANGE NOTICE DART AEROSPACE LTD

mppJob No.: RB18-EXTERNAL LOAD Date: 19.02.13 ADR Yes/No: ADR Date: N ECN# 19-579 Product No.: DART TOOLING EXTERNAL LOAD Created By: VM Approved By: SEE BELOW Product Name: Checked By: Reason for Change: INTERFERENCE BETWEEN WIRE AND WIRE CLAMP Documents Released: SWA6A REV E SWA6A-700B REV A IF APPLICABLE: NCR: PAR: CAR: CIR: **URF:** 19-579 PARTS MUST COMPLY **PAPERWORK UPDATE** PREVIOUS PARTS SATISFACTORY Quality Assurance / Customer Support Actions Resp Complete Reqd Notes Notify Previous Customers Ν 2 Notify Airbus N Notify Leonardo 3 N Manufacturing Licensing Agreement Update Ν # Resp Notes Complete **Engineering Actions** Reqd Required Documents/Drawings/Item ID's Under Review (URF) 5 N Update Master Document List (MDL) N 6 Update Document Record (DR) N Update Product Compatability Matrix 8 N 9 Notify TC / FAA of Change (eg. ICA, 8110-3) N 10 N **Document Control Actions** Reqd Resp Notes Complete 11 Move / Update Electronic Files / Design Journal N 12 Update Product Specification Files (Bluefiles) N Update Approved/Preliminary Dwg PDF Files Υ MD 9.02.20 13 Update Product Development Summary (STC applications) 14 Ν Update QSI 021 (TC/FAA STC) and/or STC Approval List N 15 Create/Update Parts / STC Database Υ MD 19.02.20 16 17 Update / Verify Authorized Release Certificate Database √N ma mt. 19.02.20 Create / Update Change Record Form / Item Card Database Create / Update Packaging Process Plan (PPP) 19 N Red Decals required on Packaging Process Plan (PPP)? N 20 21 Update Controlled Supplier Documents (Qpulse) Database N Update Grey Project Binder / Electronic Project Folder 22 N Update D-Part / M-Drawing / DSI / DEO Master Binders 23 N Update "Royalty Paid to" attribute (Parts sold under Dart USA STC's) 25 Description / Action: FOLDER NO 5fb up-3el2Hodred done h ALL STOCK NEED TO BE RE-WORK PLACE DRAWING SWA6A REV 4 IN SUPERCEED FOLDER RELEASE SWA6A REV E DRAWING RELEASE SWA6A-700B REV A DRAWING **CLOSE URF 19-579** ECN Verified & Complete:

ECN19-545 — what needs tro be reworked? Do parts need to be scrapped and changed out? Item -16, -18 and -19? — RB DB3225L — no stk on top level or sub components but a lot in wip — do any of the others need to be scrapped? Sleeve need to be added into the hose assy

ECN19-579 – is it the SWA6A or just the SWA6A-700B? what needs to be done SWA6A; wire changed, -700B added for 3 wire option

URF19-600 – has this been released yet? We have multiple sold..do parts need to be reworked? Do boms need to be updated? Ketan is working on this one, will be release next week

URF19-588 – has this been released yet? -1/-3 need to be reworked – what needs to be done? Not started yet. I will update de drawing this week

URF19-582 – has this been released yet? 11 in stock, what needs to be reworked? Mychel working on it. Should be released this week

merci

Linda Lacelle

From:

Linda Lacelle

Sent:

Wednesday, February 27, 2019 3:12 PM

To: Subject: Sylvie Boucher FW: ECN 19-579

FYI – you have w/o's open – they need to be updated

189353

189881

189883

189884

189885

Pls bring them to me to get updated

From: Daniel Paquette <dpaquette@dartaero.com>

Sent: Wednesday, February 27, 2019 2:56 PM

To: Linda Lacelle < llacelle@dartaero.com>; David Duval < dduval@dartaero.com>

Cc: Marie Lajeunesse <mlajeunesse@dartaero.com>

Subject: RE: ECN 19-579

The SWA6A-3 was using SWA6A-700A and now is using SWA6A-700B.

For all SWA6A the wire has changed. Was ARCTIC WIRE and now is TEXCAN WIRE.

For all SWA6A D2728-1 placard has been added.

From: Linda Lacelle < llacelle@dartaero.com>
Sent: Wednesday, February 27, 2019 2:32 PM

To: Daniel Paquette < dpaquette@dartaero.com >; David Duval < dduval@dartaero.com >

Cc: Marie Lajeunesse < mlajeunesse @dartaero.com>

Subject: RE: ECN 19-579

So....what do I need to do here pls?